

Shop Set, Aviation Intermediate Maintenance: Non-Divisional Armament Repair, Shelter Mounted

SC: 4940-95-B10
NSN: 4940-01-144-1437
LIN: S26335
TM: 9-4940-427-14&P

System Description

Obsolete, replaced by 4920-01-548-2317.

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

n/a

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.
- Service SKO IAW TM to 10/20 (annual service) and LO.
- Service prime mover/trailer IAW platform guidance.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568)
rock-pm-skot@conus.army.mil